Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **0592**	Model Year **1986**	License # **4260**	Rated Capacity ***** **71**
Chassis Make **GMC**	Body Make **Ward**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☑ Gas ☐ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Komenda Ent Inc**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL

School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1969**	Model Year **2004**	License # **1469**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **Other**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1BAAGCSHXMF044413**	Model Year **1991**	License # **1480**	Rated Capacity ***** **72**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Bibb Bus Lines**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1BAAHB7A3RF062495**	Model Year **1994**	License # **1484**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Kiddie Coach**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1BAAHB7A5PF055813**	Model Year **1993**	License # **9039**	Rated Capacity ***** **72**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Kiddie Coach**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1BAAHBSA1PF053015**	Model Year **1993**	License # **5446**	Rated Capacity ***** **72**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Kiddie Coach**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1BAAHC5H9RF060252**	Model Year **1994**	License # **2752**	Rated Capacity ***** **72**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Ron Zimmerman**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name		District Name	
15 Flathead		**Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
1BAAHC5HXXFO85187	**1999**	**2365**	**72**
Chassis Make	Body Make	Bus Type: (see ? for definition)	
Bluebird	**Bluebird**	☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped?	Wheel Chair Lift Equipped?		
☐ Yes ☑ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel:	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is:		
☐ Gas ☑ Diesel ☐ Other	**Ed & Edith Sanders**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1BAAHCSH6LF034750**	Model Year **1990**	License # **6692**	Rated Capacity ***** **72**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Komenda Ent Inc**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1BAAHCSH6MF041084**	Model Year **1991**	License # **1483**	Rated Capacity ***** **72**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Bibb Bus Lines**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1BAAN67A16F062494**	Model Year **1994**	License # **1485**	Rated Capacity ***** **72**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Bibb Bus Lines**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is: ☐ **Approved** ☐ **Not Approved** **Inspecting Patrol Officer:** _____ **Badge No.** _____ **Date** _____	**On reinspection, this bus is:** ☐ **Approved** ☐ **Not Approved** **Inspecting Patrol Officer:** _____ **Badge No.** _____ **Date** _____
Signature of District Official	**Date**

TR-13 Revised 11/04

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name		District Name	
15 Flathead		**Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
1BAANCPAX1F097271	**2001**	**1589**	**84**
Chassis Make	Body Make	Bus Type: (see ? for definition)	
Bluebird	**Bluebird**	☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped?	Wheel Chair Lift Equipped?		
☐ Yes ☑ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel:	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		
☐ Gas ☑ Diesel ☐ Other			

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1BAANCSH4TF067173**	Model Year **1996**	License # **1410**	Rated Capacity ***** **84**
Chassis Make **GMC**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1BAANCSHORF060763**	Model Year **1994**	License # **4229**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1BAANH7AXPF055654**	Model Year **1993**	License # **1481**	Rated Capacity ***** **72**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Bibb Bus Lines**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1BABNBBA9VF071890**	Model Year **1997**	License # **1478**	Rated Capacity ***** **72**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Kiddie Coach**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1FDPJ75P9KVAO4141**	Model Year **1989**	License # **1846**	Rated Capacity ***** **72**
Chassis Make **Ford**	Body Make **Thomas**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Ron Dyer**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1GBHG31R6W1063155**	Model Year **1998**	License # **1285**	Rated Capacity ***** **21**
Chassis Make **Chevrolet**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☑ A ☐ B ☐ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☑ Gas ☐ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1GBJG31R6V1155564**	Model Year **2000**	License # **1377**	Rated Capacity ***** **11**
Chassis Make **Chevrolet**	Body Make **Amtran**	Bus Type: (see ? for definition) ☐ A ☑ B ☐ C ☐ D	
Wheel Chair Lift Equipped? ☑ Yes ☐ No	Wheel Chair Lift Equipped? ☑ Forward Facing ☐ Aisle Facing ☐ Not Applicable		
Type of Fuel: ☑ Gas ☐ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name: **15 Flathead**	District Name: **Kalispell Public Schools**
Vehicle I.D. # (VIN) - Entire Number: **1GDKH32K6R3500933**	Model Year: **1994**
License #: **1058**	Rated Capacity *****: **11**
Chassis Make: **GMC**	Body Make: **Thomas**
Bus Type: (see ? for definition) ☐ A ☑ B ☐ C ☐ D	
Wheel Chair Lift Equipped? ☑ Yes ☐ No	Wheel Chair Lift Equipped? ☑ Forward Facing ☐ Aisle Facing ☐ Not Applicable
Type of Fuel: ☑ Gas ☐ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:
☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:
☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1HNBJABN9WA081775**	Model Year **1998**	License # **1235**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **Other**	Bus Type: (see ? for definition) ☑ A ☐ B ☐ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1HVBBAAP7SH614532**	Model Year **1995**	License # **1848**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **Other**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Fisher Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1HVBBABM2YH294078**	Model Year **2000**	License # **1440**	Rated Capacity ***** **18**
Chassis Make **International**	Body Make **Amtran**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☑ Yes ☐ No	Wheel Chair Lift Equipped? ☑ Forward Facing ☐ Aisle Facing ☐ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1HVBBABP5TH369908**	Model Year **1996**	License # **1468**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **Amtran**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1HVBBABP7SH660187**	Model Year **1995**	License # **1807**	Rated Capacity ***** **65**
Chassis Make **International**	Body Make **Other**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Patricia Fisher**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1HVBBACP5RH587368**	Model Year **1994**	License # **1477**	Rated Capacity ***** **72**
Chassis Make **International**	Body Make **Amtran**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Kiddie Coach**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name		District Name	
15 Flathead		**Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
1HVBBAP4H219658	**1995**	**1283**	**77**
Chassis Make	Body Make	Bus Type: (see ? for definition)	
International	**Other**	☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped?	Wheel Chair Lift Equipped?		
☐ Yes ☑ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel:	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		
☐ Gas ☑ Diesel ☐ Other			

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name		District Name	
15 Flathead		**Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
1HVBBAPISH219651	**1995**	**1284**	**77**
Chassis Make	Body Make	Bus Type: (see ? for definition)	
International	**Amtran**	☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped?	Wheel Chair Lift Equipped?		
☐ Yes ☑ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel:	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		
☐ Gas ☑ Diesel ☐ Other			

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1HVBBPHP8NH453525**	Model Year **1992**	License # **1938**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **Amtran**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Fisher Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name		District Name	
15 Flathead		**Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
1HVBJADR11A911805	**2001**	**1467**	**78**
Chassis Make	Body Make	Bus Type: (see ? for definition)	
International	**Amtran**	☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped?	Wheel Chair Lift Equipped?		
☐ Yes ☑ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel:	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		
☐ Gas ☑ Diesel ☐ Other			

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name		District Name	
15 Flathead		**Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
1HVBJADR7YA025725	**2000**	**1409**	**71**
Chassis Make	Body Make	Bus Type: (see ? for definition)	
International	**Amtran**	☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped?	Wheel Chair Lift Equipped?		
☐ Yes ☑ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel:	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		
☐ Gas ☑ Diesel ☐ Other			

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1HVBRABP22B919336**	Model Year **2001**	License # **1530**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **Amtran**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name		District Name	
15 Flathead		**Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
1HVBRABP82B919356	**2001**	**1531**	**71**
Chassis Make	Body Make	Bus Type: (see ? for definition)	
International	**Amtran**	☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped?	Wheel Chair Lift Equipped?		
☐ Yes ☑ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel:	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		
☐ Gas ☑ Diesel ☐ Other			

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1HVLP5VN1KH648945**	Model Year **1989**	License # **1486**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Kiddie Coach**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name		District Name	
15 Flathead		**Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
1T88R4B12V1148396	**1997**	**1176**	**71**
Chassis Make	Body Make	Bus Type: (see ? for definition)	
Other	**Thomas**	☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped?	Wheel Chair Lift Equipped?		
☐ Yes ☑ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel:	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		
☐ Gas ☑ Diesel ☐ Other			

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name: **15 Flathead**		District Name: **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number: **2506**	Model Year: **1991**	License #: **8214**	Rated Capacity *****: **71**
Chassis Make: **International**	Body Make: **Thomas**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Becker Bussing**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **40RBRABP74B964633**	Model Year **2004**	License # **1961**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **International**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Berry Transportation & Leasing**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **4DRBGAAN93A955023**	Model Year **2002**	License # **1549**	Rated Capacity ***** **51**
Chassis Make **International**	Body Make **Amtran**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☑ Yes ☐ No	Wheel Chair Lift Equipped? ☑ Forward Facing ☐ Aisle Facing ☐ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **4DRBGAANO3A955248**	Model Year **2003**	License # **1548**	Rated Capacity ***** **51**
Chassis Make **International**	Body Make **Amtran**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☑ Yes ☐ No	Wheel Chair Lift Equipped? ☑ Forward Facing ☐ Aisle Facing ☐ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **4DRBJAD34A967038**	Model Year **2004**	License # **1614**	Rated Capacity ***** **84**
Chassis Make **International**	Body Make **International**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **4DRBRAAP94B967910**	Model Year **2004**	License # **KIDS**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **International**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Berry Transportation & Leasing**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **4DRBRAAPX4B965406**	Model Year **2004**	License # **1962**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **International**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Berry Transportation & Leasing**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **5096**	Model Year **1986**	License # **4501**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **Thomas**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Becker Bussing**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **7419**	Model Year **1988**	License # **1373**	Rated Capacity ***** **72**
Chassis Make **Chevrolet**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Bibb Bus Lines**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Kalispell Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **9794**	Model Year **1985**	License # **1310**	Rated Capacity ***** **72**
Chassis Make **Chevrolet**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☑ Gas ☐ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Komenda Ent Inc**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name		District Name	
15 Flathead		**Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
1BAAGCSH3MF044415	**1991**	**1104**	**72**
Chassis Make	Body Make	Bus Type: (see ? for definition)	
Bluebird	**Bluebird**	☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped?	Wheel Chair Lift Equipped?		
☐ Yes ☑ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel:	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		
☐ Gas ☑ Diesel ☐ Other			

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BAAGCSH4MF044410**	Model Year **1991**	License # **1103**	Rated Capacity ***** **72**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BAAGCSH7MF04417**	Model Year **1991**	License # **1100**	Rated Capacity ***** **72**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BAAHCSHONF046993**	Model Year **1991**	License # **7929**	Rated Capacity ***** **72**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BAAKBSA1MF046756**	Model Year **1991**	License # **902**	Rated Capacity ***** **78**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BAAKBSAXMF046755**	Model Year **1991**	License # **7901**	Rated Capacity ***** **78**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BAANBSA1PF053959**	Model Year **1993**	License # **891**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

TR-13 Revised 11/04

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BAANBSA1TF065989**	Model Year **1995**	License # **1101**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BAANBSA4RF060598**	Model Year **1994**	License # **1059**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BAANBSA6RF060408**	Model Year **1994**	License # **7907**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BAANBSA6TF066488**	Model Year **1995**	License # **1102**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BAANBSA7PF055733**	Model Year **1993**	License # **7893**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name		District Name	
15 Flathead		**Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
1BAANBSA7VF071427	**1996**	**1151**	**84**
Chassis Make	Body Make	Bus Type: (see ? for definition)	
Bluebird	**Bluebird**	☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped?	Wheel Chair Lift Equipped?		
☐ Yes ☑ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel:	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		
☐ Gas ☑ Diesel ☐ Other			

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BAANBSA8PF053960**	Model Year **1993**	License # **587**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name		District Name	
15 Flathead		**Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
1BAANBSA8WF077156	**1997**	**1214**	**84**
Chassis Make	Body Make	Bus Type: (see ? for definition)	
Bluebird	**Bluebird**	☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped?	Wheel Chair Lift Equipped?		
☐ Yes ☑ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel:	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		
☐ Gas ☑ Diesel ☐ Other			

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BAANBSAXPF053958**	Model Year **1993**	License # **892**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BAANBSAXWF077157**	Model Year **1997**	License # **1215**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BAANCSA6VF071425**	Model Year **1996**	License # **1154**	Rated Capacity ***** **65**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☑ Yes ☐ No	Wheel Chair Lift Equipped? ☑ Forward Facing ☐ Aisle Facing ☐ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name		District Name	
15 Flathead		**Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
1BAB1CXA3GF073855	**1986**	**1293**	**84**
Chassis Make	Body Make	Bus Type: (see ? for definition)	
Bluebird	**Bluebird**	☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped?	Wheel Chair Lift Equipped?		
☐ Yes ☑ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel:	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		
☐ Gas ☑ Diesel ☐ Other			

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BABMBXA3LF038857**	Model Year **1990**	License # **7863**	Rated Capacity ***** **48**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BABMBXA7LF034200**	Model Year **1990**	License # **832**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BABMBXA9LF034201**	Model Year **1990**	License # **7836**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BABNB0A3XF089160**	Model Year **1999**	License # **1323**	Rated Capacity ***** **45**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BABNB0A3YF091492**	Model Year **2000**	License # **1361**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name		District Name	
15 Flathead		**Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
1BABNB0A43F212927	**2003**	**1544**	**84**
Chassis Make	Body Make	Bus Type: (see ? for definition)	
Bluebird	**Bluebird**	☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped?	Wheel Chair Lift Equipped?		
☐ Yes ☑ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel:	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		
☐ Gas ☑ Diesel ☐ Other			

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name		District Name	
15 Flathead		**Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
1BABNB0A43F212928	**2003**	**1543**	**84**
Chassis Make	Body Make	Bus Type: (see ? for definition)	
Bluebird	**Bluebird**	☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped?	Wheel Chair Lift Equipped?		
☐ Yes ☑ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel:	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		
☐ Gas ☑ Diesel ☐ Other			

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BABNB0A5XF089161**	Model Year **1999**	License # **7989**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name		District Name	
15 Flathead		**Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
1BABNB0A5YF091493	**2000**	**1360**	**84**
Chassis Make	Body Make	Bus Type: (see ? for definition)	
Bluebird	**Bluebird**	☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped?	Wheel Chair Lift Equipped?		
☐ Yes ☑ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel:	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		
☐ Gas ☑ Diesel ☐ Other			

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BABNB0A81F099349**	Model Year **2001**	License # **1402**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL

School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BABNB0A84F214617**	Model Year **2004**	License # **1615**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is: ☐ **Approved** ☐ **Not Approved** **Inspecting Patrol Officer:** _____ **Badge No.** _____ **Date** _____	**On reinspection, this bus is:** ☐ **Approved** ☐ **Not Approved** **Inspecting Patrol Officer:** _____ **Badge No.** _____ **Date** _____
Signature of District Official	**Date**

TR-13 Revised 11/04

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Columbia Falls Pub Schls**	
Vehicle I.D. # (VIN) - Entire Number **1BABNC0A91F099348**	Model Year **2001**	License # **1403**	Rated Capacity ***** **64**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☑ Yes ☐ No	Wheel Chair Lift Equipped? ☑ Forward Facing ☐ Aisle Facing ☐ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Creston Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1BAAHCSH4RF060255**	Model Year **1994**	License # **910**	Rated Capacity ***** **72**
Chassis Make **International**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Cayuse Prairie Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1GBL6P1G7GV100145**	Model Year **1986**	License # **2759**	Rated Capacity ***** **72**
Chassis Make **Chevrolet**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Miles of Smiles Inc**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Cayuse Prairie Elementary**	
Vehicle I.D. # (VIN) - Entire Number **XXXXXXXXXXXXX1887**	Model Year **1978**	License # **8638**	Rated Capacity ***** **72**
Chassis Make **Ford**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Miles of Smiles Inc**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Cayuse Prairie Elementary**	
Vehicle I.D. # (VIN) - Entire Number **XXXXXXXXXXXXX2381**	Model Year **1989**	License # **3292**	Rated Capacity ***** **71**
Chassis Make **Chevrolet**	Body Make **Ward**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☑ Gas ☐ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Miles of Smiles Inc**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name: **15 Flathead**	District Name: **Cayuse Prairie Elementary**
Vehicle I.D. # (VIN) - Entire Number: **XXXXXXXXXXXXX2414** / Model Year: **1981**	License #: **2762** / Rated Capacity *****: **71**
Chassis Make: **Ford** / Body Make: **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable
Type of Fuel: ☑ Gas ☐ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Miles of Smiles Inc**

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Cayuse Prairie Elementary**	
Vehicle I.D. # (VIN) - Entire Number **XXXXXXXXXXXXX6299**	Model Year **1981**	License # **2760**	Rated Capacity ***** **65**
Chassis Make **Ford**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Miles of Smiles Inc**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name: **15 Flathead**	District Name: **Helena Flats Elementary**

Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
5282	**1967**	**870**	**65**

Chassis Make	Body Make	Bus Type: (see ? for definition)
Chevrolet	**Superior**	☐ A ☐ B ☑ C ☐ D

Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable
Type of Fuel: ☑ Gas ☐ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:	On reinspection, this bus is:
☐ **Approved**	☐ **Approved**
☐ **Not Approved**	☐ **Not Approved**
Inspecting Patrol Officer: _____	**Inspecting Patrol Officer:** _____
Badge No. _____ **Date** _____	**Badge No.** _____ **Date** _____
Signature of District Official	**Date**

TR-13 Revised 11/04

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Somers Elementary**	
Vehicle I.D. # (VIN) - Entire Number **0848**	Model Year **2003**	License # **8739**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **American**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Somers Elementary**	
Vehicle I.D. # (VIN) - Entire Number **0950**	Model Year **2002**	License # **707**	Rated Capacity ***** **72**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Somers Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1BAAGCSH2TF080964**	Model Year **1988**	License # **3002**	Rated Capacity ***** **71**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

TR-13 Revised 11/04

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Somers Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1BAAHBSA7RF060960**	Model Year **1994**	License # **9080**	Rated Capacity ***** **66**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Somers Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1BAANCPA11F097272**	Model Year **2001**	License # **5933**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Somers Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1BAANCPA31F097273**	Model Year **2001**	License # **5931**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Somers Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1BAANCPA51F097274**	Model Year **2001**	License # **5932**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Somers Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1BAANCPA91F097276**	Model Year **2001**	License # **5928**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Somers Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1BAANCPAX1F097271**	Model Year **2000**	License # **8740**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Somers Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1BAANCPAX3F21**	Model Year **2003**	License # **7TE**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **American**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Somers Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1BAB1BXA3GF070951**	Model Year **1986**	License # **1345**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Somers Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1GBHG31F2W1062123**	Model Year **1998**	License # **2551**	Rated Capacity ***** **13**
Chassis Make **Chevrolet**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☑ A ☐ B ☐ C ☐ D	
Wheel Chair Lift Equipped? ☑ Yes ☐ No	Wheel Chair Lift Equipped? ☑ Forward Facing ☐ Aisle Facing ☐ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Somers Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1GDJG31F711209408**	Model Year **2001**	License # **7T**	Rated Capacity ***** **19**
Chassis Make **GMC**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☑ B ☐ C ☐ D	
Wheel Chair Lift Equipped? ☑ Yes ☐ No	Wheel Chair Lift Equipped? ☑ Forward Facing ☐ Aisle Facing ☐ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Somers Elementary**	
Vehicle I.D. # (VIN) - Entire Number **2271**	Model Year **1997**	License # **2552**	Rated Capacity ***** **28**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☑ Yes ☐ No	Wheel Chair Lift Equipped? ☑ Forward Facing ☐ Aisle Facing ☐ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Somers Elementary**	
Vehicle I.D. # (VIN) - Entire Number **3950**	Model Year **2002**	License # **4707**	Rated Capacity ***** **72**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Somers Elementary**	
Vehicle I.D. # (VIN) - Entire Number **7271**	Model Year **2000**	License # **8740**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name: **15 Flathead**		District Name: **Somers Elementary**	
Vehicle I.D. # (VIN) - Entire Number: **7272**	Model Year: **2001**	License #: **5933**	Rated Capacity *****: **84**
Chassis Make: **Bluebird**	Body Make: **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:
☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:
☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Somers Elementary**	
Vehicle I.D. # (VIN) - Entire Number **7274**	Model Year **2001**	License # **5932**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Somers Elementary**	
Vehicle I.D. # (VIN) - Entire Number **7276**	Model Year **2001**	License # **5928**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Bigfork Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **0754**	Model Year **1994**	License # **4217**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Bigfork Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1BAAECPA81F099651**	Model Year **2001**	License # **1414**	Rated Capacity ***** **32**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☑ Yes ☐ No	Wheel Chair Lift Equipped? ☑ Forward Facing ☐ Aisle Facing ☐ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name		District Name	
15 Flathead		**Bigfork Public Schools**	
Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
1BAAHCSH5NF049369	**1993**	**1042**	**72**
Chassis Make	Body Make	Bus Type: (see ? for definition)	
Bluebird	**Bluebird**	☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped?	Wheel Chair Lift Equipped?		
☐ Yes ☑ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel:	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		
☐ Gas ☑ Diesel ☐ Other			

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name		District Name	
15 Flathead		**Bigfork Public Schools**	
Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
1BAAKBSA9NF048689	**1993**	**1118**	**78**
Chassis Make	Body Make	Bus Type: (see ? for definition)	
Bluebird	**Bluebird**	☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped?	Wheel Chair Lift Equipped?		
☐ Yes ☑ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel:	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		
☐ Gas ☑ Diesel ☐ Other			

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name		District Name	
15 Flathead		**Bigfork Public Schools**	
Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
1BAANBSA2RF062396	**1994**	**1242**	**78**
Chassis Make	Body Make	Bus Type: (see ? for definition)	
Bluebird	**Bluebird**	☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped?	Wheel Chair Lift Equipped?		
☐ Yes ☑ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel:	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		
☐ Gas ☑ Diesel ☐ Other			

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name		District Name	
15 Flathead		**Bigfork Public Schools**	
Vehicle I.D. # (VIN) - Entire Number	Model Year	License #	Rated Capacity *****
1BAANCPH8YF090696	**2000**	**1343**	**84**
Chassis Make	Body Make	Bus Type: (see ? for definition)	
Bluebird	**Bluebird**	☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped?	Wheel Chair Lift Equipped?		
☐ Yes ☑ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel:	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		
☐ Gas ☑ Diesel ☐ Other			

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

TR-13 Revised 11/04

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Bigfork Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1BAANCSA85F062446**	Model Year **1995**	License # **808**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☑ Yes ☐ No	Wheel Chair Lift Equipped? ☑ Forward Facing ☐ Aisle Facing ☐ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Bigfork Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1BAANCSHXRF060745**	Model Year **1994**	License # **4217**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Bigfork Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1BABMBBA5RF089077**	Model Year **1994**	License # **2564**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Treasure State Transit**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Bigfork Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1BABNBKAX5F226198**	Model Year **2005**	License # **1668**	Rated Capacity ***** **74**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Bigfork Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1BABNBXA72F205619**	Model Year **2002**	License # **1482**	Rated Capacity ***** **84**
Chassis Make **Bluebird**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Bigfork Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1FDPJ75A1MBA32952**	Model Year **1991**	License # **4487**	Rated Capacity ***** **72**
Chassis Make **Ford**	Body Make **Other**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **John M Johnson**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Bigfork Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1HVBA18EXDHB10988**	Model Year **1983**	License # **4481**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **James & Debbie Thompson**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Bigfork Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1HVBBPEPXNH451697**	Model Year **1992**	License # **4482**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **Thomas**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **James & Debbie Thompson**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name: **15 Flathead**	District Name: **Bigfork Public Schools**
Vehicle I.D. # (VIN) - Entire Number: **1HVLNHGM3EHA49169**	Model Year: **1984**
License #: **6868**	Rated Capacity *****: **71**
Chassis Make: **International**	Body Make: **Thomas**
Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Dan Demars**

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:
☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:
☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Bigfork Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **6890**	Model Year **1987**	License # **3069**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **Other**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Carol Bjork**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Whitefish Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **1387**	Model Year **1997**	License # **2105**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Rocky Mountain Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name: **15 Flathead**		District Name: **Whitefish Public Schools**	
Vehicle I.D. # (VIN) - Entire Number: **1494**	Model Year: **1995**	License #: **4832**	Rated Capacity *****: **24**
Chassis Make: **Ford**	Body Make: **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Rocky Mountain Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Whitefish Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **3378**	Model Year **1996**	License # **2109**	Rated Capacity ***** **72**
Chassis Make **GMC**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Rocky Mountain Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Whitefish Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **3395**	Model Year **1997**	License # **2107**	Rated Capacity ***** **71**
Chassis Make **GMC**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Rocky Mountain Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Whitefish Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **4058**	Model Year **1989**	License # **2115**	Rated Capacity ***** **72**
Chassis Make **Chevrolet**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☑ Gas ☐ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Rocky Mountain Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Whitefish Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **4123**	Model Year **1998**	License # **2104**	Rated Capacity ***** **71**
Chassis Make **GMC**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Rocky Mountain Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Whitefish Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **4412**	Model Year **1991**	License # **2101**	Rated Capacity ***** **71**
Chassis Make **Chevrolet**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Rocky Mountain Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Whitefish Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **4747**	Model Year **1989**	License # **2102**	Rated Capacity ***** **71**
Chassis Make **Chevrolet**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Rocky Mountain Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Whitefish Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **5309**	Model Year **1988**	License # **2114**	Rated Capacity ***** **71**
Chassis Make **Chevrolet**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Rocky Mountain Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Whitefish Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **5427**	Model Year **1995**	License # **2108**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Rocky Mountain Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Whitefish Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **6174**	Model Year **2001**	License # **TE29**	Rated Capacity ***** **71**
Chassis Make **GMC**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Rocky Mountain Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Whitefish Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **7226**	Model Year **2002**	License # **1990**	Rated Capacity ***** **72**
Chassis Make **Chevrolet**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Rocky Mountain Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Whitefish Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **7918**	Model Year **1997**	License # **2106**	Rated Capacity ***** **72**
Chassis Make **Chevrolet**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Rocky Mountain Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Whitefish Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **8394**	Model Year **1993**	License # **2110**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Rocky Mountain Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Whitefish Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **8840**	Model Year **2003**	License # **Temp**	Rated Capacity ***** **71**
Chassis Make **GMC**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Rocky Mountain Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Whitefish Public Schools**	
Vehicle I.D. # (VIN) - Entire Number **9476**	Model Year **1990**	License # **2103**	Rated Capacity ***** **71**
Chassis Make **Chevrolet**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Rocky Mountain Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Evergreen Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1GBJG31UX51148231**	Model Year **2005**	License # **1706**	Rated Capacity ***** **19**
Chassis Make **Chevrolet**	Body Make **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☐ C ☑ D	
Wheel Chair Lift Equipped? ☑ Yes ☐ No	Wheel Chair Lift Equipped? ☑ Forward Facing ☐ Aisle Facing ☐ Not Applicable		
Type of Fuel: ☑ Gas ☐ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Evergreen Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1HVBBABP6TH369965**	Model Year **1996**	License # **290**	Rated Capacity ***** **69**
Chassis Make **International**	Body Make **Other**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Evergreen Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1JGBJP1BXKV107739**	Model Year **1989**	License # **840**	Rated Capacity ***** **65**
Chassis Make **Chevrolet**	Body Make **Wayne**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☑ Gas ☐ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name: **15 Flathead**		District Name: **Marion Elementary**	
Vehicle I.D. # (VIN) - Entire Number: **1GBG6P1B6HV112827**	Model Year: **1987**	License #: **2967**	Rated Capacity *****: **47**
Chassis Make: **Chevrolet**	Body Make: **Ward**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☑ Gas ☐ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Frye and Company**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Marion Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1GDJ6P1B7GV510592**	Model Year **1986**	License # **4260**	Rated Capacity ***** **71**
Chassis Make **GMC**	Body Make **Ward**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☑ Gas ☐ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Komenda Ent Inc**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Marion Elementary**	
Vehicle I.D. # (VIN) - Entire Number **4601**	Model Year **1982**	License # **1308**	Rated Capacity ***** **42**
Chassis Make **Chevrolet**	Body Make **Carpenter**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☑ Gas ☐ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Komenda Ent Inc**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name: **15 Flathead**		District Name: **Marion Elementary**	
Vehicle I.D. # (VIN) - Entire Number: **9794**	Model Year: **1985**	License #: **1310**	Rated Capacity *****: **72**
Chassis Make: **Chevrolet**	Body Make: **Bluebird**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Komenda Ent Inc**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name: **15 Flathead**		District Name: **Olney-Bissell Elementary**	
Vehicle I.D. # (VIN) - Entire Number: **1HVBBNMP4MH392506**	Model Year: **1991**	License #: **8214**	Rated Capacity *****: **71**
Chassis Make: **International**	Body Make: **Thomas**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Becker Bussing**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Olney-Bissell Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1HVBBNMP6MH392507**	Model Year **1991**	License # **5776**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **Thomas**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Becker Bussing**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **Olney-Bissell Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1HVLPHYM9GHA25096**	Model Year **1986**	License # **4501**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **Thomas**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Becker Bussing**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

- State ☐
- District ☐
- County ☐
- Patrol ☐
- Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name: **15 Flathead**		District Name: **Olney-Bissell Elementary**	
Vehicle I.D. # (VIN) - Entire Number: **4DRBUAAP56B203442**	Model Year: **2006**	License #: **7528**	Rated Capacity *****: **71**
Chassis Make: **International**	Body Make: **International**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Becker Bussing**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **West Valley Elementary**	
Vehicle I.D. # (VIN) - Entire Number **1GBJ6P1B2GV114112**	Model Year **1986**	License # **1436**	Rated Capacity ***** **71**
Chassis Make **Chevrolet**	Body Make **Thomas**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☑ Gas ☐ Diesel ☐ Other	Is Bus: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name: **15 Flathead**		District Name: **West Glacier Elementary**	
Vehicle I.D. # (VIN) - Entire Number: **2165**	Model Year: **1993**	License #: **1613**	Rated Capacity *****: **71**
Chassis Make: **Ford**	Body Make: **Thomas**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Byrd Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name **15 Flathead**		District Name **West Glacier Elementary**	
Vehicle I.D. # (VIN) - Entire Number **IHVBBAAP4WH524440**	Model Year **1998**	License # **1612**	Rated Capacity ***** **71**
Chassis Make **International**	Body Make **Thomas**	Bus Type: (see ? for definition) ☐ A ☐ B ☑ C ☐ D	
Wheel Chair Lift Equipped? ☐ Yes ☑ No	Wheel Chair Lift Equipped? ☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable		
Type of Fuel: ☐ Gas ☑ Diesel ☐ Other	Is Bus: ☐ District Owned ☑ Contractor Owned If contractor owned, contractor's name is: **Byrd Transportation**		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☑ 1st semester ☐ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Approved Yes	Approved No	Approved NA **	Approved Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						**Required by forest regulation:**				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. ***New buses ordered after 08/15/02.***Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Signature of District Official

On reinspection, this bus is:

☐ **Approved**
☐ **Not Approved**

Inspecting Patrol Officer: _____

Badge No. _____ **Date** _____

Date